

Bauer



Garanti: 12 ay

Bu rne ait Trkiye ii kapı teslim fiyat ve teslim sresi ieren teklifimizi almak iin info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi iin +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.

Bauer Markası, tedarik sresi iin ltfen bizimle iletiŐime geiniz.

Firmamız Bauer Trkiye Distribtr veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen rnlerde sadece Orjinal ve yeni rn teklifi sunmaktadır. Bu sitede gsterilen zel marka adları ve ticari markalar ilgili sahiplerinin mlkiyetindedir, talep durumunda kaldırılmaktadır.

| rn | Aıklama |
|---|---|
| Bs04-84/P05la32-G/E003b9/Sp | Basic type worm geared motor Make BAUER Type BS04-84 / P05LA32-G / E003B9 / SP Engine power (kW) 0.18 Painting 1K primer Article no. 188S1407 brand new This product is licensed by STEINLEN Elektromaschinenbau GmbH manufactured. Weight / piece approx .: 8.300 kg |
| Paint 45.74 Optional | Painted in RAL 1016 |
| Bf60-05a/Dpe13xa4/RI/Sp | (7.5 kW , 14.8 A, 1460 d/dk, 400 V) |
| BS06-62U/D06LA4/SP | worm geared motor Motor power (kW) : 0,25 Mounting : H1 Output shaft speed (rpm) : 9,2 / 11,5 Terminal box position : II / A Torque (max. allowed) (Nm) : 106 / 106 Dimensional drawing : BS06 Service factor fB : 1,0 / 1,0 Catalogue : DG 07 Corrosion protection : Standard net weight per unit : ca. 12 kg |
| BAU2577542 | Materialnummer 30404584 |
| BG06-31/DHE05LA4-TOF-ST/AM | 189E8908 |
| BF10-04/DPE08XB4 | Materialnummer 30674339 BCAS Artikelnummer 189F5829 Flat gear motor BF10-04 / DPE08XB4 Motor power: 0.75 kW Speed of the AW: 188 r / min Torque: 38.0 Nm Service factor fB: 4.0 Installation: H3 Terminal box position: IV / A Corrosion protection: standard Painting: RAL 7031 Dimension drawing: BF10-BF10Z Catalog: B 2010 Net weight per piece: approx. 30 kg Additional / special designs: Rating plate also stamped with: Customer ID no. E07100.7518801 With 2nd rating plate loose in the terminal box Design of the gearbox: Type: BF10 2-stage flat gear Execution code number 04 Cast on with torque arm Hollow shaft with keyway (d: 25 mm) Total reduction i: 7.58 Additional / special designs: 2 rubber buffers are supplied loose. With mounting aid -Holding- loose as an accessory pack Please note: engine The motor is connected via CAGE-CLAMP (cage clamp spring technology)! CAGE CLAMP is a registered trademark of WAGO |
| BG10-71/DV08MA4 | |

| | |
|--|---|
| BG30-11/DHE09LA4/SP | |
| BAU2519704 | Description WORK SHAFT BK30-32-A3 OUTPUT SHAFT BK30-32-A3 REAR TAP Net weight 14.211 KG |
| BAU2503140 | Description WORK SHAFT BG40-30-A3 OUTPUT SHAFT BG40-30-A3 Net weight 4.620 KG |
| BG30Z-37/DHE08MA4-TOF-ST-K/ESX010A9/AM | <p>Material number 30669180 BCAS item number 189F1499 Article number: 189F1499 Spur gear motor with single-disc spring-loaded brake BG30Z-37/DHE08MA4-TOF-ST-K/ESX010A9/AM Motor power: 0.37 kW Speed of the AW : 19.5 r/min Torque: 181 Nm Service factor fB: 1.65 Lineup: B5 Terminal box position: IV / B Corrosion Protection: Standard Paintwork: RAL 7031 Dimension drawing: BG30-BG30Z-AM Catalogue: B 2010 Net weight per piece: about 34 kg Additional/special versions: Rating plate additionally stamped with: 460VY;60Hz;0.99A;IE2-77.8%;147Nm;24r/min Customer ID no. 24377517 With 2nd rating plate loose as an accessory pack Version of the gearbox: Type: BG30Z 3-stage spur gear Version code 37 with standard flange on front side (d: 200 mm) PTO shaft on gear side V for flange version (d: 30 mm) Total gear reduction i: 73.51 Additional/special versions: with oil-resistant seal between gear housing and screwed-on flange Engine design: Type: three-phase squirrel-cage motor DHE08MA4-TOF-ST-K Rated speed: 1430 rpm Voltage: 230/400V Stator circuit: D/Y Frequency: 50Hz Rated current: 1.91/1.10 A Power factor cos phi: 0.65 Efficiency: IE2 - 75.9% (according to EN 60034-2-1) Heat class: F IP protection according to EN 60529: IP 65 IC cooling type according to EN 60034-6: IC 411 Terminal box: TBS112 Additional/special versions: Harting plug connection HAN 10 ES according to dimensional drawing TBS11.-06-A3 and connection diagram HS21100000/01: Add-on housing 09 300 100 301 - 2 brackets Pin insert 09 330 102 616 sleeve housing - socket insert - Cover 09 300 105 407 With built-in thermostats "opener" for shutdown according to insulation class F according to additional connection diagram Z010.1030-13. Design of the brake: Working brake under the fan hood Type: Single-disc spring-loaded brake ESX 010 A 9 Setting value: 10.0 Nm IP protection class according to EN 60529: IP 65 Coil Voltage: 24V Coil Current: 1.45A Additional dimension drawing: N-BR Connection voltage DC: 24 V Additional/special versions: Please note: engine Execution according to regulations DIN VDE 0530-1, IEC 60034-1 Three-phase asynchronous motor with electrical design according to NEMA and CSA regulations NEMA MG1, CSA C22.2 No. 100 (as far as applicable to geared motors), with squirrel cage rotor, with roller bearings; surface-ventilated, completely closed, Dust-tight and jet-proof according to NEMA MG1, Part 5. Rating plate with international symbols. However, the motors are not NEMA C</p> |
| BF40-65RA/DV09LA 4-TF-K/E008B9HN/SP | |
| KPL 2800 BC 35 | |
| BF40-65RL/DPE11LA4-TF-K/ES027A9/SP | 189H6695 |

| | |
|---|--|
| gear-box Bauer BK80-50VO-C/IEC160 IM H4 | |
| brake Danfoss Bauer E075B7 1954309-2 BE | |
| motor BK50-84W/D09LA4-S/ESX027A9HN | |
| motor BF40-65RL/D08MA4-TF-K/E008B9/SP | |
| motor BF90-04W/DSE18XA4-TF-G-FV | |
| motor Bauer BF40-04W/DPEU11LB4C/C5-M-SP | |
| motor Bauer BF20-04/DSE09LA4-TF | |
| gear-box Bauer BF80-00W-C/IEC180 IM H4 | |
| motor BF30-35/DSE09LA4-TF/C2 | |
| brake Bauer ZS500A9HA | |
| DNF11SA4-SP | 3 Phase,2.2kw 1400 RPM(round per minute) IP65(Protection class) 50 Hz(Frequency) |
| PE200-TE | |
| BF70-05A gear motor | |
| 189H9594 | BF70-05A/DPE18XB4/SP |
| BF50-0.4/D11 SA4-TF | m:104 |
| CFG17G71-111/D5A6-429M with Brake GBR 500 WS | |
| CFG17G71-111/D5A6-429M 7.5 kw n2: 4.9 dev/dak | |
| GBR500 WS | |
| BRAKE SOLENOID FOR MOTOR | 3NMDANFOSS BAUER |
| BRAKE DISC HS EH040 D09/ES040-D11 D13 | Material number 30404642 BCAS item number BAU2581574 BRAKE DISC HS EH040 D09/ES040-D11 D13 ALUMINUM FDW 15 T2701 ITEM.2.4 |
| BRAKE DISC HS EH027-D08/ES027-D09 | Material number 30404640 BCAS item number BAU2581558 BRAKE DISC HS EH027-D08/ES027-D09 dia.19,ALUMINUM FDW 13 T2701 ITEM.2.2 |
| BRAKE DISC HS ES070-D11-D13 | Material number 30404643 BCAS item number BAU2581582 BRAKE DISC HS ES070-D11-D13 ALUMINUM FDW 17 T2701 ITEM.2.5 |

| | |
|--|--|
| BRAKE DISC HS EH125-D11/ES125-D13-D16 | Material number 30404644 BCAS item number BAU2581604 BRAKE DISC HS EH125-D11/ES125-D13-D16 ALUMINUM FDW20 T2701 ITEM.2.6 |
| BG06-31/DHE07LA4-TOF-K/E003B4 | 189L4231 |
| Helical gear | motor type:BG70-11/DH13LA4 motor configuration:rated power 7.5 kw 1460 RPM,49 NM 400 v, 15A rated voltage:380 v AC/50 HZ 4 POLE OUT PUT SPEED:37.5 RPM |
| BK90-54VL/D18XA4S/Z100B9/SP 30KW T | |
| BS06-84/D06LA8-TOF | 189L9301 |
| BK90-54VL/DPE20XA4-TF-S/ESX250A9/SP | BCAS Artikelnummer 189M2929 |
| BG20Z-37W/DHE05LA4-D/SP | 189M3927 |
| 30767241 | 189M4170 Description ETG BG20Z-37W/D06LA4 i=157.00 V1 ETG transmission part complete with wheel 1 ETG BG20Z- 37W/D06LA4 i=157.00 V1 with preliminary stage (Replacement for #10983380-2, A/ 188P6656) |
| BK80Z-14U/D11MA4-TOF-K-Z015B9/C2-SP | |
| 0,28kW;9,2/11,5 1/min | BS06-82/D06LA4/MG 574631 |
| BAU2577542 | Material number 30404584 Description RECTIFIER, W.HOUSING SG 3.575B RECTIFIER W.HOUSING SG 3.575B |
| HMB5-1.8-1-T-3-Y-N B51T0101 | HYDRO MOTOR COMPLATE |
| U1=MAX.575VAC + %5 | |
| BG10Z-11/D06LA4W-TF/C3-SP 0,06KW | |
| 188x8164 | |
| Z 400 (Laufscheibe Für S 320) Laufscheibe | |
| 1025414 | |
| Dk94-241 | |
| Bsã216;4- 84/Dã216;4la4-Tof 0.09 Kw | |
| D1a6-283 | |
| Dk812d372/200 | |
| 659410 | |
| Zks025a2ws | |
| Bg30-11/Dhe11la4-Tf-G-K/Esx070a7/Ht1-Av-C1-Sp | |

| |
|--|
| Obsolete No Replacement - Dk840h/200 |
| Bau188j2075 |
| 188m8570 |
| 56x28,5x2,5 |
| 1038648 |
| 188p1395 |
| Bk50-Bk50z |
| Dk6406/163 0,18 Kw U:220-380v N:88min-1 F:50hz Fa.Bauer M2 ,3 Phase Reductor Motor |
| 216-3 |
| E075b9 |
| Bg80-11/D18xa4/Rr |
| Bs02-34v-D04la4 |
| 188s5186 |
| 24117031 |
| Bf50-04/Du13la4-Tf/C4-Sp |
| Ebs04-61 |
| 188b8830 |
| 188u0775 |
| G12-10/Npk830-240 /B3-6-7 |
| 173z8727 |
| G132(Ex.Fdr71a/2nco) |
| Dk 812 Ez 22/200 By Sk 573.1 - 63s/4 |
| Bs02-71 V/P04la32/Dsg-Sp |
| E075b6hn |
| Bk50z-24v/D08ma4-Xxx |
| Bf40-04/Dhe09xa4-G-Fv-S/Es010a9hn |
| Bg30-11w/Dhe11ma4-G/Ht1-Av-C1-Sp |
| 25760069-2 |
| Bk80-32h/Dhe16lb4-Tx-D-G-Fv- M/Esx200ax/Sp |

| |
|---|
| 188r7255 |
| 090100-Eu |
| 2b-70-13-26-02 |
| 393051 |
| 188n5123 |
| Bg20-11/D09xa4-Tf |
| Bk30-14u/D11sa4w |
| Bk70-14u/D16la4w |
| Cfg13 R1,R2 10/39 |
| Bk30-Bk30z |
| Dkp8420/200l |
| 1017144 |
| E075b9ha |
| Bk50-34v/D09xa4-S/Z008b8ha/Sp |
| 188j422300 |
| Bg05-11/P04la32/Em |
| Bg50-11/D11ma4w-Tf |
| 40x20,4x2,25 |
| 84,5x60,5x0,9 |
| Cfg 7g-214/Dk84-200 |
| Obsolete Bg30-11/D08la4-K/Z008b5/Sp Replaced By Bg30-11/Dse08la4- K/Esx010a9/Sp |
| Esx125a9 |
| Bg 60 -11/D13/Ma4 |
| 131h3934 |
| Bau2512564 |
| 1051300 Seal 3760 |
| G32-11/D1a6-283-W |
| Etb E008b9 |
| 173h7052 |
| 39,6x25,5x0,5 |

| |
|--|
| Bk40g10-34v/D06la4-D-S/E000389/Sp |
| 188n2414 |
| Bk80-Bk80z |
| G22-10/Dk 94-216 |
| Bs06-81/D06la4/Mg (Artikel-Nr.: 188h478700) |
| Dk Ez 11a/163 Obsolete, Replaced By Bg10-11/Dhe08la4/Sp |
| Gbr513-A4 |
| Bg06-11/Dxs05la4-Tb-S |
| 216-1 |
| Bs04-71v/P04la25-G Motor |
| 188m6808 |
| Bg40-11/D11la4-Tf-G/UI-C2-Sp |
| Bk80g40-74h/D09xa4-Tf/C1 Old Version, New Version Bk80g40-74h/Dpe09xb4c- Tf/C1 |
| Bk60-74v/D11ma4-Tf-D/C1 Old Version, New Version Bk60-74v/Dpe11la4c-Tf- D/C1 |
| 219221-15 Oem For Stoll |
| 188n5121 |
| Bg10-37/D06la4 |
| Bf 70-04/Dr16 Ma4-Tof K/E 075 B7 Ha |
| Bk70-Bk70z |
| Dnfk88/200l |
| Bs06-34v/D07la4 |
| Bk80g40-74h/Dpe09xb4c-Tf/C1 |
| 188n5119 |
| 188b0247 |
| Bau2506441 |
| 188w9660 |
| 173f728500 |

| |
|---|
| Bg60-11/D13lc84-S/Esx125a9 |
| 216-5 |
| 171z9390 Etb Eks075b6hn |
| 188b0245 |
| Bg60z-11/Dse09la4-S/Esx010a9/Sp |
| Dp6a84fqu15v-214/499 |
| 188m7429 |
| Sve220-0-Ex |
| 173f5766 |
| Bg30-11/Ma4-Tf-G/Ht1-UI-C2-Sp |
| 1011090/60x80x10mm |
| 188u0781 |
| 1304453 Seal |
| Bau2580551 |
| Bk30-35va/Dpe09xa4c |
| 25492002-1 |
| Bg80-11/DI16la4w-Tf-G/UI-C2-Sp |
| Eks0085b5ha |
| 136324 |
| Bg 70-11/D16xa4 |
| Do44-141l-S |
| 1025392 |
| Bf50-04w/Dhe11la4c/C1 |
| 188n5122 |
| D-7300 A-134520 Essling Gbzs 50 Ws No: A-13452 380 Vac |
| D04la4 |
| Bg30-11/D09xa4w-Tf |
| Bg40z-11/Dv06la4 |
| 25492054-2 |
| 011430 |

| |
|--|
| 188t9303 |
| 25492049 |
| 188u0782 |
| Bs0671v/Dv06la6-T0fst/Am-Sp B6 913943046 188k137300 |
| 133696 |
| 71,5x50,5x0,7 |
| Bau2507846 |
| Bs30z-34v/D06la4-Tf-S/E003b9/Ha/Am |
| 188s8252 |
| (188m188900) Bf80-04/D11la8-D- M/Esx070a9/Sp Gear Motor |
| 173u3230 |
| Dkf880h/200 |
| N33530 |
| 034575 |
| 173f198800 |
| Bk40-Bk40z |
| Bs06q04-54vl/D04la4/C1-Sp |
| Bq04-31/P04la32/Emv - Obsolete/No Replacement |
| Bk10-21uw/D09la4w |
| 173l1377 |
| Bs06-72h/Dv06la6-Tof-Stá; Am-Sp |
| Dia67v/283 |
| 25492020-1 |
| 188j5060 |
| 25491943-2 |
| 393 080 |
| Dk54g062sz5-2122/143l |
| Bs06-71v/Dv06la6-Tof-St Am-Sp |
| 188f220800 |

| |
|---|
| Bg30-11/Dse08la4-K/Esx010a9/Sp |
| 173l6016 |
| Bg50-11/Dr11la6/C2 |
| Dk 68 Ez 11a/163 |
| Bg 70 -11/D16la4 |
| Disc Brake Pad For Type: Abr 25dc |
| Dl6a411/499l |
| Sr-A-S-230-004 |
| G22-10/D2a4-309k-W |
| 5g3.575a Obsolete, Replaced By Bau2577542 |
| 04496/85x120x12mm;Din 3760 |
| 188u6518 |
| Bg60-11/D11 La4/Rr |
| 188b2919 |
| 124x90,5x1,25 |
| Bg10x-11/D09sa4-Tf |
| Tf-D/Ht1-C3-Sp |
| Bk60-74v/Dpe11la4c-Tf-D/C1 |
| 1025376 |
| 188k0457 Etm Bf50-04/Dhe11la4-Tf |
| T0034469 |
| 2577542 |
| 35,5x18,3x2 |
| 188g4360 |
| Gv-247v/345b |
| Bs06-74v/Dv05la4/Sp |
| 1576490 , By Ste1700043 |
| 188p0471 |
| E 2077808-1 !! By Bk30-35va/Dpe09xa4c |
| 1778875-07 |

| |
|--|
| Bk60-Bk60z |
| Bs0671v/Dv06la6-Tofst/Am-Spb6 Nr:25976371-9 |
| 72935 |
| Cooling Fan C/W Impeller For Cv3a-Cv3c |
| 31,5x16,3x1,75 |
| 216-4 |
| D2a4-309 |
| 188u0773 |
| E008b8 |
| 188n2036 |
| 188n5120 |
| Bau2508427 |
| Bg05-11/D04la4-Tf-G-/E003bhn/Sp |
| 188n2399 |
| 1017233 |
| G02-20/Dk 64-163 L Obsolete/ Replaced By Bg10-37/D06la4 |
| Bk90-Bk90z |
| Bs06-81/D06la4/Mg |
| G12-10/Npk 830-240 , No |
| Q1000351 |
| Cbzs250gs-HI Obsolete,Replaced By Zkk025a4ha (Ste1700135) |
| Bg10-11/Dhe08la4/Sp |
| Bs02-38h/D05la4/Sp |
| 25491891-1 |
| 61,5x40,5x0,7 |
| 188w7603 |
| Bg20z-11/D06la4-Tf |
| B28.2-55-Sz |
| 188k7592 |

| |
|---|
| Dnf13ma4w/Sp S/No:E2070581-1 |
| 173z7035 |
| 171z8895 |
| Bf20-04/Dhe08xa4 |
| 216-2 |
| N33525 |
| 71 605 24 C 07 |
| Z015b9 M.Bohr |
| 50x25,4x3 |
| Bf60 04 D09a4 |
| Bs06-34v/Dv05la4/Am |
| Omp315-151-0617 |
| Bg 80-11/D18la4 |
| 25x12,2x1,5 |
| Bau2506491 |
| 188g6470 |
| Bf80-04/Dhe13ma4-Tf-Fv- K/Es070a8ha/Ht1-Sp Gear Motor |
| Esx010a5 |
| Bg 80 -11/D16la4/R |
| 188s2074 |
| Bg40-11/Dhe11la4c-Tf |
| Bf 20-04/Dse 09 La 4-Tf |
| Bk30g06-24v/D05la12-Tf-S/E003b4/Sp |
| 188m6066 Etm Bs06-81/D08ma4-Tf- K307 |
| Bs06-74v/D06la4/Mg |
| 25988373-1 / By Tf-D/Ht1-C3-Sp |
| Bf90-04/Dr18xa4-Tf |
| Dk84-200 |
| Bg04 11 Du04la4 |
| Zkk025a4ha |

| |
|--|
| Bg06-31/D04la4-Tf |
| 41,6x25,5x0,45 |
| Bau188s2585 |
| Cfg13g22-111/D1a4-283m |
| 393080 |
| 1025163 |
| 3021408 |
| 188u0778 |
| Bs10-74h/D05la4 |
| 173f9566 |
| Bg10x-11/D09sa4 |
| 188r7308 |
| Bg30-11/D09la4w-Tf |
| 173n567000 |
| Bg10-37/D08xa4-Tf- |
| Bau2540801 |
| Bk20-Bk20z |
| Bg10-11/D05la4-E/E003b9 |
| 188u0770 |
| Bs03-74vh/Dv05la4 |
| 188m3565 |
| Bk10-Bk10z |
| Bf20-04/D09la4 |
| Etb E008b9hn |
| 189a0104 |
| Bs06-71v/Dv06la6-Tof-St/Am,Artikel-Nr.: 188k137300 |