

## Leeson

Garanti: 12 ay  
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in [info@yursat.com.tr](mailto:info@yursat.com.tr) e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.  
**Leeson** Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

*Firmamız Leeson T¼rkiye Distrib¼t¼r¼ veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.*



¼r¼n	A¼ıklama
<a href="#">F10g</a>	
<a href="#">C42d17fk1c</a>	KATALOG NR. 098000.00
<a href="#">M1120169.00</a>	
<a href="#">Spare Part List</a>	The parts which includede below, 5 9326441: Brake Disk Weldment 6 9326442: Brake Shoe Assembly 6.50 in. Length, 1.25 in. Width, 2.92 in. Height, Right Side 9 9325831: Brake Plate Weldment, 5.38 in. Length,7.25 in. Width, 1.88 in. Height 14 8010007: Springs, Compression Type, 0.105" Wire Diameter, 0.870" Outside Diameter, 2.00 in. Overall Length, 7 Total Coils, Spring Wire Material, Closed and Ground Spring Ends 15 9325980-REPLACEMENT: BRAKE CYLINDER ASSEMBLY SA 3,4,7,8,10,11,12,13,16,17,18 Screw nuts and washers
<a href="#">Type: C4t17nc46a</a>	Leeson Model#: 102861.00
<a href="#">Leeson Model#: C6T17DK33</a>	Catalog#: E116763.00 Weight: 37 LB
<a href="#">3/4 Hp - 1725 rpm</a>	

<a href="#">10191402 2BK55H</a>
<a href="#">C6T17FC164B</a>
<a href="#">C112t17fz1c</a>
<a href="#">102861 Cycle Motor</a>
<a href="#">Model: Cm34d27fz5a (Oem)</a>
<a href="#">C145t14fc6d Motor</a>
<a href="#">C180t11fz1ccc 005a Ac Electric Motor</a>
<a href="#">C6c17wk (Alternative Is 191479.00)</a>
<a href="#">C184t14f137c</a>
<a href="#">C6t34fk36f</a>
<a href="#">P21134 - Motor</a>
<a href="#">M1900010.28</a>
<a href="#">M4c34sdh16 (Oem)</a>
<a href="#">Cm34d25nz207a Oem</a>
<a href="#">Propeller To Cool The Pump Leeson C143t34fc2f</a>
<a href="#">108046 Motor</a>
<a href="#">Model No: Cm34d36nz6a-12 Volt (Oem)</a>
<a href="#">101729.00 (Oem)</a>
<a href="#">Zyt 124/19 2,5 Hp</a>
<a href="#">C6t14fc7c</a>
<a href="#">101729.00 (Oem) Motor</a>
<a href="#">191479.00</a>
<a href="#">5104053 I06e (Obsolete - Replaced By 5104053 I06e Modified) Gear Motor</a>
<a href="#">113909.00</a>
<a href="#">193307.60 Motor</a>
<a href="#">Carbon Brush For Mr 16634 Rev E Obsolete</a>
<a href="#">098198 00 Kk2171, Model C42d34ob20b (Obsolete - No Replacment)</a>
<a href="#">192209 00</a>

<a href="#">103001202</a>
<a href="#">145t14fb13d</a>
<a href="#">05860 M 1135065 00</a>
<a href="#">C42d17nz18a</a>
<a href="#">121277 00</a>
<a href="#">A4517dz32c Oem</a>
<a href="#">108046</a>
<a href="#">028505 00</a>
<a href="#">C42d17fk5d</a>
<a href="#">110035-00 Obsolete Repl. By 116757.00 Motor</a>
<a href="#">Cat.No.098379.00, Mod. C42d17fc31a, Type Df, Frame Nss56c</a>
<a href="#">C90t34fz2ccc</a>
<a href="#">193346.60</a>
<a href="#">K254c 1-4</a>
<a href="#">5104053 I06e Modified</a>
<a href="#">050332 Cv 415 V</a>
<a href="#">2309778</a>
<a href="#">Model: Cm34d20nz5b Oem</a>
<a href="#">C4d28nk8e</a>
<a href="#">C42d340t11h !!</a>
<a href="#">01337 M190 0010 47</a>
<a href="#">098198 00 Kk2171, Model C42d34ob20b (Obsolete - No Replacment) Motor</a>
<a href="#">108047</a>
<a href="#">C145t14fb13d</a>
<a href="#">Cm34d36nz6a (Oem)</a>
<a href="#">C256t17bb6c</a>
<a href="#">C180t11fz1c</a>
<a href="#">C215t17fk3c</a>
<a href="#">C42d17fk47a (Alternative Is C42d17fk5d) Motor</a>

<a href="#">Zyt 124/19 2 Hp - Oem</a>
<a href="#">2309778cc</a>
<a href="#">C6t17dk3e</a>
<a href="#">C145t14fc5c Motor</a>
<a href="#">192051.30</a>
<a href="#">C4d34db6c (Obsolete No Rpl.)</a>
<a href="#">C4t17fz20b Obsolete Replaced By Cat.192051.30</a>
<a href="#">192051.30 Iec Metric Motor</a>
<a href="#">C145k14dc2b Oem Motor</a>
<a href="#">Leeson-Federn-F3;R-C4d34db3c- Istanbul-Turkiye</a>
<a href="#">C145k14dc2b</a>
<a href="#">900 015.7</a>
<a href="#">5104053 I06e (Obsolete - Replaced By 5104053 I06e Modified)</a>
<a href="#">900 007.02</a>
<a href="#">Cm34d25n, Cat No:M1135302</a>
<a href="#">C80t17fz43</a>
<a href="#">05712 192038 00</a>
<a href="#">C4t14fh18</a>
<a href="#">C4d28nk8a</a>
<a href="#">102861</a>
<a href="#">140155.00</a>
<a href="#">C42d17fk47a (Alternative Is C42d17fk5d)</a>
<a href="#">116757.00</a>
<a href="#">Coal Spring For K254c 1-4</a>
<a href="#">C6t17nz42f</a>
<a href="#">102867 00</a>
<a href="#">02263 098 008 00</a>
<a href="#">Cat No: 108.640.00, Model C4d28nk8e Oem For Spx Hydraulic Technologies</a>

[C112111fz20](#)

[C4d34dz14a](#)

[C80t17fz43ac](#)