

Benshaw

Garanti: 12 ay
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.
Benshaw Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

Firmamız Benshaw T¼rkiye Distrib¼t¼r¼ veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.



| ¼r¼n | A¼ıklama |
|--|----------------------------|
| Benshaw | |
| CONTACTOR COIL BENSRAW NEMA SIZE 6 RSC 600 110V AC | AC-DC 0751C |
| CONTACTOR BENSRAW NEMA SIZE 6 RSC 600 110V AC-DC | |
| EMX4i-0115B-511 55KW | |
| EMX4i-0200B-511 90KW | |
| EMX4i-0069B-511 37KW | |
| EMX4i-0105B-511 45KW | |
| Rx3e-250-480-12kp | 250 HORSEPOWER |
| Ncfvnrn32-3r-22 | STARTER NEMA5 FULL VOLTAGE |
| Bibpc720 | |
| Spo-B40 | |

| | |
|------------------------------------|---|
| Mx2pb-075-4-4-Cbpy | |
| Rc3-0-S-180a-34c | MX3 TECHNOLOGY |
| Pc10005901 | PC BOARD |
| Rsi-005-Gx-2 | |
| Spo-22-1a3 | |
| Rsi-001-Gx-2 | |
| Rsd6606c | BOARD |
| Rsi005sx6b | DRIVE 5HP 600V 3PHASE SX NEMA1 |
| Kpmx3slcd | |
| Rsc220u120 | |
| Con-100016-00 | |
| Con-100016-01 | |
| Rx2e-500-480-12kp | NEMA 12 -500 HORSEPOWER |
| Rsi-050-Sg-4-B | NEMA 1 /PROTECTED CHASIS 460V |
| Rc-130a-56ac110 | |
| Bipc-300052-01 | |
| Rsc-A4 | |
| Asy-Kpmx3cbl2m | |
| Spo-22-5 | |
| Rc3-0-S-156a-34c | MX3 TECHNOLOGY |
| Rsi-001-G-4 | |
| Bipc-300040 | |
| Rc2-0-S-027a-31c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rc2-0-S-302a-35c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Dcb3-5-480-C | INJECTION BRAKE 5HP 22.8AMP 480V 60HZ |
| Bipc-M1pwr-D4 | |
| Rsi-002-Gx-4 | |
| Rsi-020-S-4db | 20HP 460V AC DR |
| Rbx-1-S-240a-15c | |
| Rb3-1-S-477a-17c | MX3 TECHNOLOGY |

| | |
|--|--|
| Spo-85-74 | |
| Electric Power Contactor Rsc-300 | |
| Rsi040h4l | DRIVE |
| Rc85a56ac120 | |
| Rmso32h33a | |
| Rsc220u120 | |
| Rb3-1-S-052a-12c | MX3 TECHNOLOGY |
| Rsi-005-S4-2w | 5HP 230V AC DR |
| Rc2-0-S-515a-36c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Pc-100051-02 | POWER SUPPLY BOARD |
| Rx2e-050-480-3rkp | NEMA 3R -50 HORSEPOWER |
| Spo-22-0.33 | |
| Rsi-200-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Rsd404801 | CONTROLLER |
| A1411012 | |
| Rsi-020-S-44w | DRIVE VARIABLE FREQUENCY 20HP 27AMP 460VAC NEMA 4X |
| Rsd6-200-6-1 | |
| Rx2e-200-480-3rkp | NEMA 3R -200 HORSEPOWER |
| Spo-22-6.5 | |
| Bict5005 | |
| Rs6-50-480-C | SOLID STATE MOTOR CONTROL 50HP 68AMP 480VAC 60HZ |
| Rsc-100-U120 | |
| Rsc-220,Ac-1-275a | |
| Rb2-1-S-027a-11c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rx2e-150-480-3rkp | NEMA 3R -150 HORSEPOWER |
| Bipcd Cib1 | |
| Rb3-1-S-838a-20c | MX3 TECHNOLOGY |
| Rsi-060-Sg-4-B | NEMA 1 /PROTECTED CHASIS 460V |
| Rsc-85/4-6ac-120 | |
| Rsi-075-H-4-L | |

| | |
|---|--|
| Rr3b-UI | |
| Spe-22???? | |
| Rsi-020-S4-6w | NEMA 4X/12 600 V |
| Rsi050s46w | |
| Rsc-100- U120 (- No) | |
| Cable Control For H99100329 Mt48t58 70pc1 | |
| Biscr8801830 | |
| Bipcrs6-420ts | |
| Rb21s250600h12cb | CONTACTOR |
| Kpmx3llcd | |
| Rx3e-050-480-12kp | 50 HORSEPOWER |
| Mx2sep250vdc1001 | MOTOR CONTROL |
| Rx3e-600-480-3rkp | NEMA 3R -600 HORSEPOWER |
| Rsd6-7.5-480-4 | DRIVE 7.5HP 11AMP 3PHASE 480VAC 60HZ |
| Pc-100050-03 | CONTROL BOARD 460VAC |
| Rsi-001-S4-4w | NEMA 4X/12 460 V |
| Rsi-100-S4-4w | NEMA 4X/12 460 V |
| Bipcrs6ak5 | TRIGGER |
| Ct10000501 | |
| Rsc-75,Ac-1-110a | |
| Bit4601820 | |
| Rx3e-150-480-3rkp | NEMA 3R -150 HORSEPOWER |
| M183brd3b6-155a-480-C | |
| Bipcm1pwr-11-05 | |
| Cfmvrnx12-300-300- | |
| Rb2-1-S-838a-20c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Pc-200059-01-00 | PC BOARD W/DIGITAL DISPLAY |
| Bipc30004008tk | CONTROL BOARD |
| Scr 100027-02-133 141744 | |

| | |
|------------------------------------|--|
| Bipc-300032-1 | |
| Biscr7012x | |
| Rsi-003-G-2 | |
| Bipcbi2-Ats | |
| Rbx-1-S-052a-12c | STARTER SOLID STATE 3PH 50HP 52AMP 600VAC 10KA |
| Rsc-32-6ac120 | |
| S20060587812 | |
| Cbrsm6sb-500-480-1 | |
| Rsi-007-Sx-4b | |
| Rb3-1-S-156a-14c | MX3 TECHNOLOGY |
| Bipcd30000501 | |
| Dcb3-25-480-C | INJECTION BRAKE 25HP 102AMP 480VDC 60HZ |
| Rsi002sx4d | CONTACTOR |
| Rsi-125-Sg-4-B | NEMA 1 /PROTECTED CHASIS 460V |
| Re-100053-00 | |
| Bisp-Lv-Scr880 | |
| Con10001601 | INLINE CONTACTOR |
| Rx2e-100-480-12kp | NEMA 12 -100 HORSEPOWER |
| Spo-40h-30a | |
| Rsi-200-S4-4d | NEMA 12 460 V |
| Pr-T-288-S | |
| Rb2-0-S-096a13c | |
| Rsc-85-56ac120 | |
| Spo-40 | |
| Bipcrs6 | |
| Rsc-300-U120 | |
| Bipc3004701 | GATE CARD |
| Rx3e-400-480-3rkp | NEMA 3R -400 HORSEPOWER |
| Rx2e-100-480-3rkp | NEMA 3R -100 HORSEPOWER |
| Rsc-85/4 | |
| Rsc-600-U120 | |

| | |
|-------------------------------------|---|
| Rsi-125-S4-6d | NEMA 12 600 V |
| Rc3-0-S-240a-35c | MX3 TECHNOLOGY |
| Rs6v-10a-230-12-Rws | MOTOR CONTROLER 10AMP 230V 60HZ |
| Mx2pb20044cbst | MODULE |
| Rsm6b-300-480-C | |
| Spe-22-22a | |
| Mvrxe18416012 | STARTER |
| Rc2-0-S-096a-33c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Bipc300030tk | BOARD |
| Rsi-040-S4-4w | NEMA 4X/12 460 V |
| Re-1414 | |
| Rsca1 | |
| Fu-805 | |
| Rsi-003-S4-2w | NEMA 4X 230V |
| Rc2-0-S-125a-34c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rsi-001-S4-6w | NEMA 4X/12 600 V |
| Rsc-100-56ac100-240 | THERMAL OVERLOAD |
| Re-100052-00 | |
| Rb2-1s302a15c | |
| Rx2e-200-480-12kp | NEMA 12 -200 HORSEPOWER |
| Rsi-015-Sx-4b | |
| Rsi-060-S4-6w | NEMA 4X/12 600 V |
| Cpt-100094-00 | |
| Lxa10015109 | |
| Rb2-1-S-180a15c | S/S STARTER |
| Rc2-0-S-361a-35c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rc3-0-S-077a-32c | MX3 TECHNOLOGY |
| Cdrs6-346a-460-1 | |
| Bipcrs6akox | |
| Rc3-0-S-052a-32c | MX3 TECHNOLOGY |

| | |
|--|--|
| Rsd620041 | SOFT START |
| Rc2-0-S-052a-32c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rsc-18-6ac120 | Contactora Model Type: |
| Rsd6-050-4-C | |
| Spd-06sz-56ac120 | |
| Spo-40h-30 | |
| Rx2e-400-480-3rkp | NEMA 3R -400 HORSEPOWER |
| Spo-40-19 | |
| Rbx1s180a14c | STARTER |
| Rsi-002-S4-2w | NEMA 4X 230V |
| Rx3e-300-480-3rkp | NEMA 3R -300 HORSEPOWER |
| Rsc656ac120 | |
| Rx3e-150-480-12kp | 150 HORSEPOWER |
| Rsc-12-6ac120 | Contactora Model Type: |
| Rc3-0-S-302a-35c | MX3 TECHNOLOGY |
| Rms-C32-As | |
| Rx3e-125-480-3rkp | NEMA 3R -125 HORSEPOWER |
| Rb21s030480s12cb | SOFT START |
| Rc2-0-S-077a-32c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rsi-150-S4-4d | NEMA 12 460 V |
| 40300102 | STACK |
| Rx2e-250-480-3rkp | NEMA 3R -250 HORSEPOWER |
| Rb2-1-S-361a-16c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Size-4 Rsc-150 Ac3-150 Amp | |
| Rsi-020-Sg-6b | 15 HP /600 VAC DRIVE WITH A NEMA 1 ENCLOSURE |
| Bipc3000408 | |
| Rb2-1-S-400-460-H-12-Cb-Op | CONTACTOR |
| Bisplv-Mx2 | |
| Pd-100345-00 | |
| Bipc-300004-04 | PC BOARD TRANSMITTER FIBER OPTIC |

| | |
|--|--|
| Re-100059-00 | |
| Rsc-40-Relay | |
| Rdb6-840a8c | |
| Rb21s077a13c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Biscr16112x | |
| Bipc-M-Rl | |
| Rsi030s2db | |
| Rb3-1-S-302a-15c | MX3 TECHNOLOGY |
| Rsc-600-6ac120 | |
| Bipcdmsr20 | |
| Rc3-0-S-040a-31c | MX3 TECHNOLOGY |
| Bict26401m | |
| Fu-100033-02 | |
| Rx3e-075-480-3rkp | NEMA 3R -75 HORSEPOWER |
| Rx3e-250-480-3rkp | NEMA 3R -250 HORSEPOWER |
| Rdb6-75-480-12-20 | |
| Rsi-150-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Fa-100038-00 | |
| Bipc-300003-01 | |
| Rms-C35 | |
| Lcd10000000 | |
| Rx3e-125-480-12kp | 125 HORSEPOWER |
| Bipc-300047-Bipc-300047-01 | |
| Rsca100 | |
| Rb2-1-S-065a-12c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Biscr5016x | |
| Rb2-1-S-200-600-H-12-Cb | SOFT STARTER 200HP 192AMP 575VAC ENCLOSED |
| Pr-T-288-C | |
| Rsi-025-Sg-4-B | 25HP 460V AC DR |
| Cfmvrmx18-1000-4160-1 | |

| | |
|--|---|
| Bipcrs6-Ox | |
| Rbx-1-S-361a16c | |
| Biscr335018100 | |
| Rx3e-050-480-3rkp | NEMA 3R -50 HORSEPOWER |
| Rc3-0-S-125a-34c | MX3 TECHNOLOGY |
| Rc2-0-S-156a-34c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Bipc-300040-01 | CPU 16MHZ MICRO II |
| Rs6-50-5-12 | MOTOR CONTROL 54AMP 575V 60HZ H0HP 3PHASE |
| 3000550105 | BOARD |
| Spo-22-15 | |
| Bipc-300010-01 | |
| Rsd6-20-480-C | DRIVE 20HP 27AMP 3PHASE 480VAC 50/60HZ |
| Rx2e-125-480-12kp | NEMA 12 -125 HORSEPOWER |
| Pc10002400 | BOARD |
| Rsi030sg4b | NEMA 1 /PROTECTED CHASIS 460V |
| Fu-760 | |
| Cfrs6-40-480-1-2m0-2m1 | |
| Spo8530a | |
| Spo-22h-2.1 | |
| Pd-100145-00 | |
| Scr1708 | |
| Cb-Lal36400 | CB,400A,600VAC,SQ.D.,22K |
| Rsd6-10-480-4 | STARTER 10HP NEMA 4 ENCLOSURE |
| Rx3e-500-480-3rkp | NEMA 3R -500 HORSEPOWER |
| Rsi-500-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Bipcrs6aks | RS6 FIRING BD |
| Ct40000002 | |
| Mvrmx3 X 3,300 V | |
| Rc3-0-S-065a-32c | MX3 TECHNOLOGY |
| Rx2e-125-480-3rkp | NEMA 3R -125 HORSEPOWER |

| | |
|---|--|
| Rsc300 | |
| Rsc-100 Ac3-105 Amp | |
| Rsi-003-S4-4w | NEMA 4X/12 460 V |
| Rb2-0-S-180a14c | STARTER 180AMP 3PH 600VAC |
| 00835051 | BRAKE |
| Bipc300010-08 | PROCESSOR BOARD |
| Rc3-0-S-477a-35c | MX3 TECHNOLOGY |
| Spe-22-5a | |
| Enc-Mv0156 | |
| Bipc-300010 | |
| Rsi-002-Gp-4b | |
| Battery For H99100329 Mt48t58 70pc1 | |
| Bipc30000401 | PC BOARD |
| Scr1719 | |
| Pc10005500 | |
| Bipc 300007 | |
| Cfrs6-50-480-1-2m0-2m1 | SOLID STATE MOTOR CONTROL WITH ENCLOSURE 50 HP |
| Brakecontrol | |
| Rsc600u120 | CONTACTOR |
| Fu-100047-00 | |
| Rx2e-150-480-12kp | NEMA 12 -150 HORSEPOWER |
| Rc65a56ac120 | |
| Rsd6604c | MODULE |
| Biscr1321-2x | |
| Rb3-1-S-180a-14c | MX3 TECHNOLOGY |
| Dcb3-50-480-C | DC BRAKE |
| Bipc-300005-01 | |
| Rc2-0-S-065a-32c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rb2-1-S-414a17c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rc2-0-S-590a-36c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |

| | |
|--|--|
| Rsi-001-Gx-4 | |
| Spd-06sz | |
| Rsc-800-U120 | |
| Rsc-85 Ac1=135 A Ac3=85 A | |
| Bipcdm30000501 | |
| Rsi-Sg-0-200-480-Sd-01-Cb-Op | DRIVE |
| Bepabipccm1lcd () | |
| Rc2-0-S-477a-35c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rsi-015-S4-4w | DRIVE S4 VECTOR 15HP 30.9/25.8AMP 3PH 460VAC |
| Com-100000-01c | |
| Rb21s240a15c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Ipf12543rf | |
| Rx3e-500-480-12kp | 500 HORSEPOWER |
| Rbx1s156a14c | STARTER |
| Spo-22-0.82 | |
| Rsc-A2 | |
| 10110001701-V1.6 | DRIVE BOARD |
| Tx-2301a | |
| Mx2sep-125vdc-300a-3-S-C | STARTER SOLID STATE DRIVE 300AMP 3PH 125V 60HZ |
| Rb31s400480h12nc | STARTER |
| Bipcrs6akolad | |
| Rsi-125-S4-4d | NEMA 12 460 V |
| Vfdskcrkpassbr | |
| Bipc30004901 | |
| Rsi-250-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Rb21s030480s3rcb | SOFT START |
| Bipc-300047-01 | |
| Rsc226ac120 | |
| Rsi-003-G-4 | AC Variable Speed Drive |
| Rsi-040-Sg-2-B | NEMA 1 230V |

| | |
|--|-----------------------------------|
| Rsi003s46w | NEMA 4X/12 600 V |
| Rbx0s414a17c | |
| Rb33s2250480h3rcbhaade | MOTOR STARTER 250HP MX3 |
| Rs6-5hp-4-12-X-X | |
| Fu-765 | |
| Rx3e-075-480-12kp | 75 HORSEPOWER |
| Spo-40h-11a | |
| Rsi-007-Sg-2-B | NEMA 1 230V |
| 170m1569d | |
| Rsc-18-6ac24 | |
| Rsc-?150 (- No) | |
| Spo-125-107 | |
| Fu10004301 | FUSE 18R 2.75KV |
| Rsc-9-6ac24 | |
| Rsi-040-S4-6w | NEMA 4X/12 600 V |
| Cfmvrmx18-550-4160-1 C/W | |
| Rb21s400600h12cb | CONTACTOR |
| Rsi-001-S4-2w | NEMA 4X 230V |
| Rx2e-075-480-12kp | NEMA 12 -75 HORSEPOWER |
| Rsi-007-S4-2w | NEMA 4X 230V |
| Kpmx3cbl2m | |
| Bict50001 | |
| Scr1739a01 | |
| Ncfvnrn80556ac120 | |
| Bipcdvdt-1/1l | |
| Rsi-015-S4-2w | NEMA 4X 230V |
| Bipc300050-02 | CONTROL CARD FOR RBX STARTER |
| Rsc-40-6ac120 | |
| Rc100a56ac120 | |
| Dcb3-10-600-C | INJECTION BRAKE 10HP 13AMP 600VDC |
| Spo4019a | |

| | |
|---|---|
| Biscr2101-2x | |
| Spo-22-8.5 | |
| 1001-00 | |
| Rsc-C406-Ac120 | |
| Rsc-85-6ac24 | |
| Bc4250a460c4m3 | |
| Spo-22-2.1 | |
| Bipc-300013-01 | |
| Rsi-003-Gx-2 | |
| Fuse Bt, 5a, 600vac, Class Cc, Atqr | |
| Spo-85-65 | |
| Spo-22h-3.3 | |
| Rs1020480c5m05m1 | |
| 450100-01-05 11228070042 | |
| Spe403pr40a | |
| Rsi-005-S4-4w | 5HP 460V AC DR |
| Rsc-9m-6ac120 | |
| Bipc-300030-01 | POWER BOARD |
| Rsm6125480c | CONTROL |
| Spo-22-0.52 | |
| Rx2e-400-480-12kp | NEMA 12 -400 HORSEPOWER |
| Rc2-0-S-180a-34c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rsi-100-S4-6w | NEMA 4X/12 600 V |
| Bipcrs6ha | |
| Rsd6-20-480-4 | STARTER 20HP NEMA 4 ENCLOSURE |
| Mx2sep-125vdc-050a-3-S-C | |
| Rx2e-300-480-12kp | NEMA 12 -300 HORSEPOWER |
| Spe-22-1a5 | |
| Rsi-040-Sx-4b | |
| Cbrsd6sb-100-480-12 | |

| | |
|--------------------------------------|---|
| Rs1005gp4b | |
| Bipcrs6bak | |
| Rsc-400 | |
| Rsd6-30-6-12 | MOTOR CONTROL 30HP 34AMPS 600V 60HZ |
| Rs6-25-480-C-3m0-3m2 | |
| Rsi030s44w | NEMA 4X/12 460 V |
| Bipc-300055-01 | GEAR MOTOR STARTER CARD LOW VOLTAGE MX2 |
| Rsi-600-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Rs620041 | |
| Bipc-300004-02 | TRANSMITTER FIBER OPTIC |
| Rtft40002400 | DRIVE |
| Rsc-180,Ac-1-230a | |
| Rx3e-200-480-3rkp | NEMA 3R -200 HORSEPOWER |
| 12010-7k | |
| Rsi-350-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Bipc-400100-01 | |
| 312-Rs6-75-4-12 | |
| Scr-1708 | |
| Rc3-0-S-027a-31c | MX3 TECHNOLOGY |
| S200204120-1 | |
| Fu-812 | |
| 287851 | |
| Rb2-1-S-600-600 | |
| Rsc326ac24 | |
| Rsd6-25-480-4 | DRIVE 25HP 34AMP 3PHASE 480V 60HZ |
| Rsi-020-S4-2w | NEMA 4X 230V |
| Spo400h200a | |
| Bimv-860-4800 | |
| Rbx-1-S-096a-13c | |
| Rsi003sx4d | DRIVE |

| | |
|--|-----------------------------------|
| Rtft40002208 | CONVERSION KIT |
| Rb3-1-S-590a-18c | MX3 TECHNOLOGY |
| Bipcrs6-C | |
| Bipc-300032-01-1 | |
| Bipc-300014-01 | |
| Bibpc720lt | |
| Redistart Micro Ii | |
| Rsi-005-S-4 | |
| Rsc-100 Ac1-160 Amp | |
| Rsd625600c | SOFT STARTER 600VDC 3PHASE 27AMPS |
| Rsi-150-S4-6d | NEMA 12 600 V |
| Rsi-700-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Rsi-200-S4-6d | NEMA 12 600 V |
| Bipc-300016-02 | |
| Rc3-0-S-515a-36c | MX3 TECHNOLOGY |
| Rs6-5-2c | |
| Bipc-Micro-Lcd | |
| Rsi-075-S4-6w | NEMA 4X/12 600 V |
| Rsc180 | |
| Ncfvnrn18127a56ac120 | |
| A480r6r1 | |
| Rb3-1-S-720a-19c | MX3 TECHNOLOGY |
| Mvrmx24-2300kw-10000-1 | |
| Bipc-300029-01 | |
| Rx3e-200-480-12kp | 200 HORSEPOWER |
| Rsc-32-6ac240 | |
| Bipc30000005 | |
| Rsc-75-6ac120 | |
| Rsc-400-U-120 | |
| Rsi-010-S4-4w | NEMA 4X/12 460 V |
| Rc3-0-S-361a-35c | MX3 TECHNOLOGY |

| | |
|---|--|
| Ct10000000 | |
| Rsi-020-Sg-2-B | NEMA 1 230V |
| Rb3-1-S-027a-11c | MX3 TECHNOLOGY |
| Bipcm1cpu | |
| Rsi-030-Sg-2-B | NEMA 1 230V |
| Rb3-1-S-361a-16c | MX3 TECHNOLOGY |
| Rsm6-50-480-C | |
| Rsi-020-Sx-6b | DRIVE VARIABLE FREQUENCY 20HP 600V |
| Rsi-040-Sg-4-B | NEMA 1 /PROTECTED CHASIS 460V |
| Rsi-015-S4-6w | NEMA 4X/12 600 V |
| Rtft-0007-03 | CONTROL |
| Rb3-1-S-040a-11c | MX3 TECHNOLOGY |
| Rx3e-400-480-12kp | 400 HORSEPOWER |
| Rb2-1-S-250-460-H-12-Cb-Op | CONTACTOR |
| Fv-R-N-018-480-1-Nc-A-H7a5-Op | STARTER 7.1AMP PRI 480V SEC 120V NEMA1 |
| Spo-B22 | |
| Spe223sr5a | |
| Rsc-32-6ac480 | Contactora Model Type: |
| Rb2-1-S-156a-14c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Mx2sep-250vdc-030a-3-S-C | MOTOR CONTROL 30AMP 0/250V 5KA |
| Rsi-100-Sg-4b | 100H 460V AC DR |
| Tp-10-01 | |
| Rmb6-110a-2c | MOTOR CONTROL SOFT START 110AMP |
| Bipc 300055-01-09 | |
| Rx2e-050-480-12kp | NEMA 12 -50 HORSEPOWER |
| Rsc600 | CONTACTOR |
| Rb2-1-S-515a-17c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rsi-020-Sx-4b | 20HP 460V AC DR |
| Rsd6-200-4-C | |

| | |
|--|--|
| Rs6-250-480-1-20-3m0 | STARTER SOLID STATE |
| Rb2-1-S-125a-14c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rb3-1-S-077a-13c | MX3 TECHNOLOGY |
| Rsi-060-S4-4w | NEMA 4X/12 460 V |
| Spo-22h-2a1 | |
| Rsc-C220-U120 | |
| Rs6v-10a-480-C | |
| Expfee | |
| Rb3-1-S-240a-15c | MX3 TECHNOLOGY |
| Rb2-1-S-052a-12c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rx2e-300-480-3rkp | NEMA 3R -300 HORSEPOWER |
| Bit4801820 | |
| Bipcm1pwr-A4 | |
| Rsm6ul-50-480-C | |
| Rea-Kdrb45l-C1 | |
| Rsi-200-Sg-6 | 200HP / 600V WALL MOUNT DRIVE |
| Bipcrs6-Bc | |
| Rb2-1-S-180a-14c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rx3e-300-480-12kp | 300 HORSEPOWER |
| Size-4 Rsc-150 Ac1-210 Amp | |
| Rc2-0-S-414a-35c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rc-130a-56ac220 | |
| Spo-B85 | |
| Rc3-0-S-096a-33c | MX3 TECHNOLOGY |
| Bipc-450100-01 | CARD SET MX3/IO MV VARIATION |
| Rtft40002303 | KIT |
| Rb3-1-S-065a-12c | MX3 TECHNOLOGY |
| Rb21s52a12c | STARTER |
| Bipcmbc1 | BYPASS |

| | |
|---|--|
| Rsc-220-U120 | |
| Bict6005 | |
| Bipc30003001tk | BOARD |
| Bipc6 | |
| Bicp-200052-01 | |
| Spo40h15 | |
| Rsi-002-Gx-2 | |
| Re-1434 | |
| Com-100188-00 (- By Con-100016-00) | |
| Rb2-1-S-590a-18c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rbx1s414a17c | STARTER |
| Spe-22 No | |
| Rs6-5-4-4x | |
| Spo-85-42 | |
| Rsm6b-200-575 | SOFT STARTER 200HP 192AMP 575VAC ENCLOSED |
| Bipc-300034-01 | |
| Rs1060sg4b | DRIVE |
| Bipc-Mlcd | |
| Rs6v-10a-4-C | CONTROLLER SS STARTER 10AMP 480V |
| Rmsc9as | |
| Rsi-010-S-4 | 10HP 460V AC DR |
| Bipc-300040-08 | |
| Bipc-300030-08 | |
| Bipcdrvdt3mv | |
| Rsi007s4 | |
| Rsi-Sg-Control-Board | DRIVE BOARD |
| Rsi-010-Sx-4b | 10HP 460V AC DR |
| Rs6-40-480-1 | |
| Rsi-010-S4-6w | NEMA 4X/12 600 V |
| Rs1025s44w | |

| | |
|--|--|
| 10306-02 | |
| Rsi003sx4b | |
| Bipc-300004-03 | |
| Rsi-150-H-4-L-12v | |
| Bipcm1pwr | |
| Bipc-300055-02 | |
| Rsi-025-S4-6w | NEMA 4X/12 600 V |
| Rsi-075-S4-4w | 75HP 460V AC DR |
| R96-0205at | |
| Bipcvsr-Flr | |
| Rsc-50-6ac240 | Contactor |
| Rtft40003501 | POWER BOARD |
| Gx-Nema1-Kit-A | |
| Rx3e-100-480-3rkp | NEMA 3R -100 HORSEPOWER |
| Spo-22-19 | |
| Spo-40h-34 | |
| Rx2e-250-480-12kp | NEMA 12 -250 HORSEPOWER |
| Rx3e-100-480-12kp | 100 HORSEPOWER |
| Rsi003gx4 | |
| Rs6-20-5-12 | MOTOR CONTROL 575V 22AMP 60HZ 20HP 3PHASE |
| Rmb6-210a-4c | MOTOR CONTROLLER SOFTSTART 210AMP |
| Rsi-002-S4-6w | NEMA 4X/12 600 V |
| Rs6-250-4-1 | STARTER SOLID STATE |
| Rb2-1-S-040a-11c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rsd6-40-480-C-13m1 | DRIVE 52AMP 480V 60HZ 40HP |
| Bipc-300047-02 Benshaw Card Mv- 5/7.2kv Fiber Optic Hard Gate ? By Bipc- 300047-01 - | |
| Rsm71548012 | MOTOR |
| Rsi-025-S-4db | DRIVE CONTROL 25HP 18.5KW 39A 3PH 460VAC .5-400HZ |

| | |
|---|--|
| Bict57601m | |
| Atdr5 | |
| Bipcrs6-Ak | |
| Rsi-020-Sg-4b | |
| Rea10008401 | REACTOR |
| Spo-125-67 | |
| Rx2e-600-480-12kp | NEMA 12 -600 HORSEPOWER |
| Rc20s240a35c | LOW VOLTAGE SOLID STATE STARTERS, CONTINUOUS DUTY |
| Rs6-250-4-12-20 | |
| Rs6-40-4-1 | |
| Rsi-005-S4-6w | 5HP 575V AC DR |
| Rsi-015-S-4db | DRIVE 15HP/11KW O/P:0-460VAC 3PHASE 24AMP .5-400HZ |
| Cbrdb64771 | |
| Rsi-002-S4-4w | NEMA 4X/12 460 V |
| Bipc30004008l | CARD CAGE |
| Dcb3-15-480-C-7m1-Rws-7m12 | |
| Rb3-1-S-125a-14c | MX3 TECHNOLOGY |
| Rc3-0-S-414a-35c | MX3 TECHNOLOGY |
| Rsc-125 U120 / Rc-130a-56ac120 Or Rc-130a-56ac220 | |
| Bipc-300030-14 | |
| Rsc-150-U120 | |
| Ri10000900 | |
| Rsc-180-U120 | |
| Rsi-010-Sg-2-B | NEMA 1 230V |
| Rmsp-Da-32ha | |
| Pcrs6bak | |
| Rb2-1-S-096a-13c | OPEN CHASSIS STARTERS WITH INTEGRAL BYPASS STANDARD DUTY 200-600V |
| Rsi-025-Sg-2-B | NEMA 1 230V |
| Rsis015s2 | DRIVE |
| Pc10000500 | |

| | |
|-----------------------------------|---------------------------------------|
| L142 | |
| Rc856ac120 | |
| Rc-C100-56ac120 | |
| Rsc-32 | |
| Rsc-300 | Contactora |
| Rx2e-600-480-3rkp | NEMA 3R -600 HORSEPOWER |
| 835051 | |
| Rsi-050-S4-4w | NEMA 4X/12 460 V |
| S-450100-00 | |
| Rsd6404801 | DRIVE |
| Bisp-Lv-Scr1500 | |
| Rsi-025-S4-4w | NEMA 4X/12 460 V |
| Cbrsd6-60-480-3r | |
| Rsc-400-U120 | |
| Spo-85-34 | |
| Bipcb12-Ats | |
| Rx2e-075-480-3rkp | NEMA 3R -75 HORSEPOWER |
| Rc3-0-S-590a-36c | MX3 TECHNOLOGY |
| Rsc-600-6ac127 | CONTACTOR 630AMP NEMA-6 100-127V COIL |
| Spo-22-A33 | |
| Rsi-010-S4-2w | NEMA 4X 230V |
| Rsi-025-S4-2w | NEMA 4X 230V |
| Rsi-001-S4-1sw | 110V SINGLE PHASE |
| Spo-22h-7a5 | |
| Bipc-300016-01 | 6 SCR FIRING BD |
| Rb3-1-S-096a-13c | MX3 TECHNOLOGY |
| Rsc ? 22 Ac3=22 | |
| Rsc 100 U120 | |
| Bipc-300030-03 | |
| Rsm7100480c | |

| | |
|-----------------------------------|--|
| Rsi-015-Sg-2b | |
| Rsi-010-Sg-4-B | NEMA 1 /PROTECTED CHASIS 460V |
| Pc10000200 | |
| Rsi-400-Sg-4 | NEMA 1 /PROTECTED CHASIS 460V |
| Rms-P32h1a | |
| Rsi010sx2b | VFD |
| Rc-130a-56ac120 | |
| Rx3e-600-480-12kp | 600 HORSEPOWER |
| Bipc300020 | |
| Spo-22-6a5 | |
| Bipc-300048-01-2 | |
| Rsd63044 | SOFT START |
| Rs71004c | |
| Rsi-075-Sg-4-B | 75HP 460V AC DR |
| Bipc-300030-04 | |
| Re-1431 | |
| 400100-01-09 | I/O CARD SET MX3 LV VARIATION |
| Rsi-003-S-4 | DRIVE AC SENSORLESS 9.6AMP 230V 3HP 10-DIGIT INPUT |
| Rsc-400u120 | |
| Bibpc720t | |
| Rsc-40 | |
| 5000886 | |
| Rsi-007-S4-4w | NEMA 4X/12 460 V |
| Rcx0s027a31c0 | STARTER |
| 810023-02-09 | |
| Spo-85-30 | |
| Rsc-22-6ac120 | |
| Rsc-9-6ac120 | |
| Rx2e-500-480-3rkp | NEMA 3R -500 HORSEPOWER |
| Bipc-300048-01 | |
| Rs6-75-460-12 | STARTER SOLID STATE 104AMP 75HP 460V 60HZ |

| | |
|--|---|
| Rsc-50-6ac120 | |
| Cfsmvrmxatl-250-4160-1 | |
| Rsc-125-U120 | |
| Rb3-1-S-414a-17c | MX3 TECHNOLOGY |
| Pc10000400 | |
| Spe-22-A5 | |
| Bipcmrev | |
| Rsi-007-S4-6w | NEMA 4X/12 600 V |
| Ncfvnrn3000250u120 | STARTER NEMA5 FULL VOLTAGE NON-REVERSE 120-230VAC |
| Rb3-1-S-515a-17c | MX3 TECHNOLOGY |
| Rsi-030-S4-6w | NEMA 4X/12 600 V |
| Bisp-Lv-Scr660 | |
| Rsc-22-Ac3 | |