

Indumart

Garanti: 12 ay
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.
Indumart Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

Firmamız Indumart T¼rkiye Distrib¼t¼r¼ veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.



¼r¼n	A¼ıklama
Pn: T12t4-4	0-160 Celsius.
Model: Pst400-14g112	Indicating pressure transmitter / Switch 0 ~ 400 bar
PST600-15-3	Indicating pressure Transmitter
PSP116-1R	PRESSURE SWITCH Rang 0 to 16 bar Pmax 70 bar
P/Ns11-3-0a10	
Dg50-Xbx100bar/P	
Battery Powered Digital Thermometer Order Code: Dt 50- Xtb2120 With Length Extension Cable 1m	
Tsm320-06b11 Length:200mm Diameter:10mm	
T37 T4pn 1/2	
P29 T6mk	

LsII?005.1	
LsII?004.1	
Ptf116x-V1g1-31	
P11-T4 0-2.5 Bar 1/2??	
P11-T4 0-16 Bar	
Pt100,3wire	
Dt50-Xtb2120 Cable Length Extension 2m	
Pressure Indicator	
Uca 890	
Fst140-W 3 Length:40mm	
Lsl?008a	
Lsl?008b	
Dt50-Xtb2120	
Battery Powered Digital Thermometer Order Code: Dt 50- Xtb2120 With Length Extension Cable 2m	
Hca870/L	
Battery Powered Digital Pressure Gauge: Rangr: 0-20bar	
Ptf116x-05g1-31	
Type 74I1-Wasngb1d, Range 0-10 Bar	
Pte215-2k-010	
Mpr3211221118 - Obsolete, Replaced By Vgr600	
Diu 70	
T37	
Scl100	
52114	S/N 44/08
Dg50-Xbx20bar/Psi	
Sem210	
St257	
Pti806	

[Battery Powered Digital Pressure
Gauge: Rangr: 0-100bar](#)

[Uca850](#)

[Fst140-I3 Length:40mm](#)

[32114](#)