



List-Magnetik

Garanti: 12 ay
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.
List-Magnetik Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

Firmamız List-Magnetik T¼rkiye Distrib¼t¼r¼ veya temsilcisi deĐildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.

¼r¼n	A¼ıklama
Magnetic Field Meter MP-1000	for measuring DC and AC fields Measurement units: A/cm - Gauss (Oe) Applicable measuring probes: axial probes P-A2 and P-W2, Tangential probes P-T2 and P-Z2 Measuring range constant field: 0-20,000 A/cm Measuring range AC: 20-20,000 A/cm Accuracy: in the homogeneous field ± 1 A/cm to 50 A/cm, $\pm 2\%$ of reading from 50 A/cm Guarantee: 12 months Customs tariff number: 9031 8080 Scope of delivery: MP-1000 without probe, with probe cable and Case, including calibration certificate. The measuring probe must be ordered separately.
Axial field probe P-A2	for magnetic field measurement with MP-1000 and MP-2000 Measuring range: 0-20,000 A/cm 0-20,000 gauss 0-2d Guarantee: 3 months
Precision calibration standard 180 A/cm	for checking the measuring accuracy of a magnetic field measuring device with axial or tangential probe Reference value: 180 A/cm Guarantee: 12 months
	for measuring constant and alternating fields Measurement units: A/cm - Gauss (Oe) Usable measuring probes: Axial probes P-A2 and P-W2, Tangential probes P-T2 and P-Z2

[MP-1000](#)

Measuring range of constant field: 0-20,000 A/cm Measuring range alternating current: 20-20,000 A/cm Accuracy: in a homogeneous field ± 1 A/cm to 50 A/cm, $\pm 2\%$ of the measured value from 50 A/cm Warranty: 12 months Customs tariff number: 9031 8080 Scope of delivery: MP-1000 without probe, with probe cable and Case, including calibration certificate. The measuring probe must be ordered separately.

[Tangential field probe P-T2](#)

for magnetic field measurement with MP-1000 and MP-2000
Measuring range: 0-20,000 A/cm 0-20,000 Gauss 0-2 d

[Pfn52ds](#)