

Securiton

Garanti: 12 ay
Bu ¼r¼ne ait T¼rkiye i¼i kapı teslim fiyat ve teslim s¼resi i¼eren teklifimizi almak i¼in info@yursat.com.tr e-posta adresine baŐvuru yapabilir ya da ayrıntılı bilgi i¼in +90 224 240 03 04 numaralı telefonumuzdan bizlere ulaŐabilirsiniz.
Securiton Markası, tedarik s¼resi i¼in l¼tfen bizimle iletiŐime ge¼iniz.

Firmamız Securiton T¼rkiye Distrib¼t¼r¼ veya temsilcisi deėildir. Firmamız sipariŐ durumunda, belirtilen ¼r¼nlerde sadece Orjinal ve yeni ¼r¼n teklifi sunulmaktadır. Bu sitede g¼sterilen ¼zel marka adları ve ticari markalar ilgili sahiplerinin m¼lkiyetindedir, talep durumunda kaldırılmaktadır.



¼r¼n	A¼ıklama
Mcd 573 Detector, W/O Base	Manufacturer Part Number 30-5000003-02-02 DETECTS SMOLDERING, GLOWING SMOKE
ASD532	
SSD 535-3 for WTU	Highly sensitive smoke sensor for ASD 535
SSD 535-3 ASD 535	
DFU 911	
Usb 502-5	
Scp 2000	
30-5000003-02-02	
Outdoor Siren With Flashing Light	
Remote Indicator Light	
B5 Bfp	

Type Scd 563
Spare Glass For Mcp 545x - , By Cpg 845
Usb 501-1 5000547-0001
Bre 535
Scp 3030
Sdi 82x-1
B5 Mmi -Fip
Internal Sirens
Bse 535
Ssd 531--No
Ssd 573 5000610-0111
Bx-01/1
Detetor De Incêndios Mcd573
Usb 502-1
Bsd 535
Tcd-563-1
Sd-Card
Mmd-130 Ex-I
Sdi 82x
B5-Scp3020
Scd 573
B5-Mic711
Bx-I2
Mcd573x
Securifire 3000
Mdi 82
B3-Mmi
Mcd 573-- By Mcd 573x (30-5000003-02-02)
Usb-502-7-Ex-I
Scd 563

Mcd 573x (30-5000003-02-02)
Mcp-535x-1.
Usb 501-1
Usb502-1 Dedektr Tabani
Bx-O2i4
Mcd573x Yangin Dedektr
Scd 563 5000610-0111
Mcp 545x-1an
Bx-Mdi8.
Mcd 573 X
Efire-Esb
B5-Baf
Mdi 82-1
Mcp 521-1n
B5-Im4
Usb 501-1 - Obsolete, Replaced By Usb 502-1
B5-Net2-485
Utd 521
Mcd 573x
Cpg 845
Mcp545x-1n Adresli Buton
Securifire 2000 Bs-Scp 2020
Sdi 82-1
Bx-Rel4
Mcp545x-1
Base For Surface Mounting And Built-In Isolator
Bx-Im4
Bx-Aim